




Mature Vegetation Retained (above) (facing west, slope covered by trees and vegetation)




Rear deck on main home and pathway, facing west, with mature vegetation (above)




Facing rear of property, DADU site is upslope, one of significant trees retained, shown (above)




From DADU site, facing north towards house, showing slope (above)



Facing east, showing mature vegetation thickness and pathway (above)



Site of proposed DADU (formerly was play structure) (above)



Southeast corner, with portion of DADU site, depicting southeast neighbor's white shed along property  $\prime$  fence line (above)